




## **ROPE ACCESS SERVICES** Cable Pulls at Height

## Instrumentation Cable Installation

- Project included installation of 360 feet of cable in three locations within a short timeframe.
- The team of 3 rope access technicians created access, pulled and secured the cables in 3 days.
- No operational interferences during this project.







## **Fiber Optic Cable Installation**

- Project included the installation of approximately 1,000 ft. of fibre optic cable.
- An Integrated team of rope access technicians and electricians were tasked to perform the work.
- The team of 4 rope access technicians pulled the cable and secured it to the existing cable tray in 3 days.
- No operational interferences were experienced during this project.

SCAFFOLD I INSULATION I FIREPROOFING I PROTECTIVE COATINGS I ABRASIVE BLASTING I ROPE ACCESS ABATEMENT I FACILITIES MAINTENANCE I MANUFACTURED PRODUCTS I OPERATIONS SUPPORT