



ROPE ACCESS SERVICES Confined Space Rope Access

The Problem

 The scaffolding and mechanical repair team were not able to access the area from below while the overhead hazard was unsecured.

The Solution


- Brock mobilized an integrated team of mechanical trades, NDE inspectors and rope access technicians to solve the problem in under 36 hours.
- The team developed the confined space rope access, rigging and rescue plan.
- They secured the overhead hazard by cutting rigging points and installing rigging under the guidance of the clients engineering team.
- Secured the failed steel in three locations and arrested any cracking to prevent further failure.


Rope Access Benefits

- Quick mobilization time to site.
- 48 hours to access and secure the failed steel.
- Reduced shut down time of client's assets.

Cost Savings

- \$150,000/day of lost production while this asset is shut down.
- Our quick response time allowed for a significant time and cost savings on this project.





SCAFFOLD I INSULATION I FIREPROOFING I PROTECTIVE COATINGS I ABRASIVE BLASTING I ROPE ACCESS
ABATEMENT I FACILITIES MAINTENANCE I MANUFACTURED PRODUCTS I OPERATIONS SUPPORT