



## ROPE ACCESS SERVICES

### Mechanical Support During Turnarounds

#### Project Summary

- Brock was hired for the removal and installation of piping from process tower during a critical turnaround.
- A four-person rope access team was used to support and assist with this complex work scope.
- The team installed pipe guides, welded supports, NDE inspections on weld locations and application of insulation.
- This complex project was completed within a two week period.
- No operational interferences were experienced during this project.

#### Rope Access Benefits

- The rope access system allowed for access to this confined space that may not otherwise be accessible using traditional scaffolding.
- The 200-foot height exposure made the logistics of the job challenging and could not have been accomplished within the same timeframe if other work access methods were used. Rope access allowed for an integrated team covering all work scopes needed on the project. During the turnaround.



SCAFFOLD | INSULATION | FIREPROOFING | PROTECTIVE COATINGS | ABRASIVE BLASTING | ROPE ACCESS  
ABATEMENT | FACILITIES MAINTENANCE | MANUFACTURED PRODUCTS | OPERATIONS SUPPORT